

DESIGN & SPECIFICATION CONSIDERATIONS EXPANSIVE PARTICLES



Expanded lime particle.

WHAT ARE EXPANSIVE PARTICLES?

They are small fragments of naturally occurring material, expansive in nature, of a size large enough to cause disruption to the surface of a brick when it expands slightly with the absorption of moisture.

CAUSE & EFFECT

The presence of potentially expansive particles in clay deposits containing compounds such as Gypsum, Siderite and Lime, is quite common in the brick Industry. Occurrence is usually controlled during factory processes as the particles are either ground too finely during clay preparation to cause problems, eliminated during firing, or are situated well beneath the surface of the brick where they are quite harmless. Occasionally, due to a combination of factors, small particles can be deposited on or near the surface of the brick face.

After firing, when the brick absorbs moisture, a chemical reaction takes place. The particles swell which, if close enough to the surface may cause portions of the brick face to “pop” off.

The results are small pits in the surface of the brick with a white (lime) or purple (siderite) spot in the centre.

This is not uncommon. It is strictly an aesthetic issue and will not affect the structural integrity of the brick. It is only the loss of a small portion of the surface of the brick and the exposure of the differing body colour underneath which causes concern.

‘Surface blows’ usually occur during construction due to hydration, or in the first few months of the life of the brick once it has come into contact with moisture, whether in the form of rain or general atmospheric damp conditions. It is unlikely to continue to develop for much longer after the occurrence has been noticed.

We recommend that all brickwork should be viewed from approximately 3 metres away. Appearance of brickwork will vary significantly with the type of clay brick chosen. The guidelines suggest 10m as a viewing distance and also suggest the size of expansive particles or chips is limited to 15mm in diameter.

REMEDICATION

To overcome the aesthetic issue, the following remedial treatment can be performed;

The expanded particle is drilled out to provide a more substantial key for a filling material. The depression is then filled with a suitable material, such as a compound of a cementitious/resin nature, which is coloured to closely match the original brick colour and additions of various sands etc. are used to provide a similar texture.

The filler is then cured and if any further work is required to more closely resemble the brick surface this is then done. The whole surface of the brick including the filled area is then tinted to blend in with existing brickwork.

Note : Although the instructions contained in this publication and any other information published by Radha-krishna Bricks Industries are indicative and strictly for guidance only. RKBi accepts no liability in relation to their use or for any losses, what so ever caused. The Buyer is fully responsible for taking all reasonable steps and safe guard the use of the products.

For further information please contact

R.K. House, Opp. Power House, Godhra. 389001. India. | T : +91 2672 260261 / 262854 | M: +91 98250 48755 | +91 98254 22020
E : jagdish.katiya@gmail.com | info@radhakrishnabricks.com | W : www.radhakrishnabricks.com