




SITE PRACTICE AND TROUBLESHOOTING **CRAZING**



The effect of crazing is not uncommon to dense, strong wire-cut bricks especially if they have a smooth face finish. It is, however, far more noticeable on smooth blue types of

The crazing is as a result of the stresses set up on the surface of the bricks when the material cools after the semivitrification that takes place during the high temperature firing.

Crazing or the effect of fire crazing is often referred to as firecracking or webbing and can be of a simple hairline crack or as a fine web-like pattern.

It is often superficial and will not detract from the overall performance. The fine hairline cracks, although unnoticeable during selection, are certainly a part of the character of the bricks. The changing weather conditions simply aggravate the crazing to a degree when they become most apparent, especially after saturation when the moisture may remain in the cracks for far longer periods of time.

A Publicly Available Specification which is intended to cover aspects of aesthetics.

ALC brickwork should be viewed from approximately 3 metres away, and deliveries of bricks should be compared to a reference panel agreed by all parties at the start of work, thought to be representative of current production and quality.

guidelines suggest 10m as a viewing distance, cracks should not be 'significant' and brickwork viewed as a whole and not on an individual basis.

Note: Although the instructions contained in this publication and any other information published by Radha-krishna Bricks Industries are indicative and strictly for guidance only. RKBI accepts no liability in relation to their use or for any losses, what so ever caused. The Buyer is fully responsible for taking all reasonable steps and safe guard the use of the products.